

# Underhill Tracker™

T-400

Portable Irrigation Machine

## Troubleshooting Guide

May 2014



**Underhill International Corporation**  
20505 Crescent Bay Drive • Lake Forest, CA 92630  
Phone: 949-305-7050 • Fax: 949-305-7051  
[www.underhill.us](http://www.underhill.us)



T-400


Portable Irrigation Machine

## Table of Contents


Valve is not Closing.....	2
Valve is not Opening.....	3
Sprinkler is not Turning.....	4
Machines Operates Too Slowly.....	5
Rope is not coiling up.....	6

# Underhill Tracker™

T-400




## Valve is Not Closing




# Underhill Tracker™

T-400



## Valve is Not Opening




# Underhill Tracker™

T-400



## Sprinkler is Not Turning




**Underhill International Corporation**  
20505 Crescent Bay Drive • Lake Forest, CA 92630  
Phone: 949-305-7050 • Fax: 949-305-7051  
[www.underhill.us](http://www.underhill.us)

# Underhill Tracker™

T-400




## Machine Runs Too Slowly




**Underhill International Corporation**  
20505 Crescent Bay Drive • Lake Forest, CA 92630  
Phone: 949-305-7050 • Fax: 949-305-7051  
[www.underhill.us](http://www.underhill.us)

# Underhill Tracker™

T-400



## Rope is not Coiling Up



**Underhill International Corporation**  
 20505 Crescent Bay Drive • Lake Forest, CA 92630  
 Phone: 949-305-7050 • Fax: 949-305-7051  
[www.underhill.us](http://www.underhill.us)