



### 250 Barb Loss Curve



### 400 Barb Loss Curve



### 700 Barb Loss Curve

